

# Agricultural Engineering Building

Herrick Archives Number 298

## A. IDENTIFICATION & LOCATION

### 1. Name


1.1 Never officially named by Board of Trustees.

1.2 Alternate names noted:

None.

### 2. Location

2.1 Located at 590 Woody Hayes Drive. See map below.



For identification of other buildings shown, see Appendix A.

### 3. General Description

3.1 Type of construction:

Reinforced concrete and load-bearing concrete block. Steel roof framing. Brick exterior.

3.2 No. of stories:

Two stories.

3.3 Area of building:

105,090 sq. ft. gross; 85,749 sq. ft. net assignable

## B. PLANNING & CONSTRUCTION

1. Building designed by Firestone Jaros Mullin, Inc.

2. Bids received on February 27, 1985.
3. Contractors, as reported to Board of Trustees on April 5, 1985:
  - General: Peterson Construction Co.
  - Plumbing: R.H. Reeb Co.
  - Heating, ventilating, & air conditioning: Duckworth Mechanical
  - Fire protection: Central Fire Protection Co.
  - Electrical: Buckeye Electric
4. Construction started on May 6, 1985. (A)
5. Building was ready for beneficial occupancy in mid-December 1986. (A)

### C. COST

Total estimated project cost as reported to Board of Trustees on April 5, 1985 is \$11,560,000.

### D. PHOTOGRAPHS

1. In Photoarchives (This building is shown under construction):

X 30191

X 30192

X 30193

John H. Herrick  
December 18, 1986